# SECRET.

## TAB A - HAHOI - LAO CATA RAIL LINE

Location	Target Number	Name	Dete	Status
220900N - 10423232 25X1		Lang Bun RR Bridge over Ngoi Bon (150 x 8 ft.; 2-span, steel bridge)	26-27 Aug 65	Both spans were dropped by 26 August; 27 August photography verified; no reconstruction attempt noted as late as 19 September; restored by 9 October; restoration time 20 days or less; bridge out of service at least 33 days but not more than 44 days.
			Inte Oct (precise date-unk- nown)	Restruck and confirmed on 29 October that 80 ft. of bridge was down; no restoration noted until bridge was again confirmed as operational on 9 November; restoration time 11 days or less; bridge out of service less than 11 days.
			12 Dec 65	Restruck but without post strike photo coverage, however, bridge was confirmed as operational by 20 December photography.

DIA review(s) completed.

SECRET

## TAB A - HANOI - LAO CAI RAIL LINE

Location	Target Number	Name	Date	Status
2206 193 10426285		Leng Bo RR Bridge No. N. Over Ngoi Ly  (58 x 18 ft.; single span steel bridge)	22 Oct	Destroyed 22 October and confirmed 29 October that the span was dropped at both ends; no reconstruction was attempted until after 12 November; restored by 21 November; restoration time 9 days or less; estimated out of service for at least 24 days but not more than 30 days.
25X1	•			HOE HOLE MISH JA GRADE

SHORE

### TAB A - HAMOI - LAO CAI RAIL LINE

Location	Target Number	None	Date	Status	٠
2201030N		Kang Kay RR Bridge Ov		Destroyed 21 October and confirmed by photography of 29 Ocrober the NW end of span was down; no	
10423302	· ,	Ragoi Key	and the second second	repair attempted until after 13 novemen; comminate	
25X1		(76 x 15 ft.; single span steel bridge)		maining; repair time 8 days or less; estimated out of service at least 25 days but not more than 31 days.	

#### TAB A - HANOI -LAO CAI RAIL LINE

TAB A - HAROT -LEW CAT RATE GLES				
Location	Tagget Number	<u> Fane</u>	<u>Date</u>	Status
220235N 1043025E		Lang Kay RR Bridge Ov Ran Linh (55 x 15 ft.; 2-span 1/2 steel truss)	18 Oct	Destroyed and confirmed on 29 October that the span was dropped from both abutments; no reconstruction until after 21 Keyember; restored by 3 December; restoration time 11 days or less; estimated out of service at least 37 days but not
		The preen crupal		more than 46.

SECRET

### TAB A - HANOI LAO CAI RAIL LINE

Location	Target Number	Name	Date	Status
220140N 1043120E		Long Khay RR Bridge Ov Hgoi Kay	19 Oct	Struck on 19 October and confirmed destroyed on 29 October; no reconstruction attempted as late
25X1	**	(92 x 9 ft.; single span steel girder)		as 21 November; new bridge in place by 3 December; restoration time 12 days or less; out of service at least 33 days but not more than 45 days.

SECRET

## TAB A - HANOI-LAO CAI RAIL LINE

			7510 6177 564771	AJALIA
Location	Target Number	Name	<u>Date</u>	Status
21-58-591/ 104-34-25E 25X1	:	Trai Rut RR Br NW over Ngoi Cho (single span 75' x 8' steel bridge)	22 Jul 65	Struck 22 July and confirmed destroyed on 5 August; reconstruction first noted on 21 August with a new bean type bridge under construction and about 1/2 complete; new bridge completed and operational by 8 September; restoration time less than 48 days; out of service at least 35 days but less than 48 days.

SERET

# TAB A - HAROI-LAO CAI RAIL LINE

Togetten	97	to a section of the s	22.02 1210 C/U	WATE PINE
Location	Target Number	Karie	Date	<u>Status</u>
21-58-30N		March 19 by march 19		3-0C-01/13
104-35-22E		Trai Hut RR BR N Over stream	Probably	Date of strike is unknown but was confirmed
		(30' x 15' single		The state of the s
25X1		span steel bridge)		The state of the s
:-				restoration time 12 days or less; out of service for unknown number of days.
				to the country of cays.

### TAB A - HANOI-LAO CAI RAI LINE

Location	Target Number	Name	Date	Status
21-56-401/ 104-37-203		Song Dong Dep RR Bridge Kam Moui	Between 12-28 Sep	Date of strike unknown; confirmed as destroyed and replaced by a new bridge by photography of 9 October.

25X1

DAR A - HAMAT-YAA CAT RATT, LITTE

<u>Location</u>	Target Number	Kane	Date	Status
21-54-55N/ 104-39-295		Lang Quach RR Bridge N over Ngo1 Va1	31 Jul	Struck and destroyed on 31 July; confirmed on 5 August; new bridge operational by 8 September; restoration time less than 39 days.
25X1		(75° x 15° single span steel through truss)		
			21 Oct	Restruck on 21 October and confirmed as destroyed by 29 October photography; no reconstruction attempted as late as 9 November; new bridge in place by 23 November; restoration time 14 days or less; out of service at least 22 days but less than 33 days.
			5 Dec	Although reported attacked on 5 December no

### TAB A - HANOI - LAO CAI RAIL LINE

Location	Target Number	Name	Date	Status
215355N 1044022E		Lang Quach Ngoai RR Bridge Ov Ngoi Quach	`24 Aug	Struck and destroyed on 24 August; 8 September photography revealed a new bridge in place and operational; restoration time was less than 15
25X1		(62 x 8 ft.; single span steel bridge)	e.,	days and it was out of service less than 15 days.

#### TAB A - HAUOT-LAO CAT RATE TIME

Location	Tarnet Eusber	Name	Date	Status
214419H 1045032E		Go Dong RR Bridge over Stm (88 x 15 ft.; single	16 and 22 Jul, 22 Aug	Struck between 16 and 22 July and again on 27 August; photography of 22 July revealed some damage to bridge and photography of 22 September revealed a new structure in place and operational.
25X1		spon steel truss)		Time necessary to restore to service was less than 26 days.